

AUG-23-04 13:45 FROM: FL GUEST HOUSE  
TO: [REDACTED] RECD BY: [REDACTED]

PAGE 3/5

Page 1 of 1

UE I  
Crandall Crandall  
E+A

**Boyce, Barb**

From: Hill, Bruce [REDACTED]  
Sent: Monday, March 12, 2007 1:16 AM  
To: Murray, Bob; Moore, Robert  
Subject: Crandall

Mr. Murray,

As you know, Crandall has been pulling pillars in excess of 2,000 feet cover. Regular bumping has been occurring, but the pillar integrity was adequate for continued operations. Today, the section suffered a significant bump (no one was hurt) and the stopping line into the face was destroyed. The conditions are too unstable to send men in to correct the problem without a massive, expensive effort. Consequently, the section is being pulled and moved to the south side of the mains. The section should be operating by the second shift on Monday. In total, we lost 11 crosscuts of pilfering.

cc: [REDACTED]

3/12/2007

UEICONG-K000038554